

AFRL-RX-WP-TM-2010-4112

COLLABORATIVE RESEARCH AND DEVELOPMENT (CR&D)

Delivery Order 0040: Bearing Health Monitoring Research and Development

Sara Gudorf

Universal Technology Corporation

FEBRUARY 2008 Final Report

Approved for public release; distribution unlimited.

See additional restrictions described on inside pages

STINFO COPY

AIR FORCE RESEARCH LABORATORY
MATERIALS AND MANUFACTURING DIRECTORATE
WRIGHT-PATTERSON AIR FORCE BASE, OH 45433-7750
AIR FORCE MATERIEL COMMAND
UNITED STATES AIR FORCE

NOTICE AND SIGNATURE PAGE

Using Government drawings, specifications, or other data included in this document for any purpose other than Government procurement does not in any way obligate the U.S. Government. The fact that the Government formulated or supplied the drawings, specifications, or other data does not license the holder or any other person or corporation; or convey any rights or permission to manufacture, use, or sell any patented invention that may relate to them.

This report was cleared for public release by the USAF 88th Air Base Wing (88 ABW) Public Affairs Office (PAO) and is available to the general public, including foreign nationals. Copies may be obtained from the Defense Technical Information Center (DTIC) (http://www.dtic.mil).

AFRL-RX-WP-TM-2010-4112 HAS BEEN REVIEWED AND IS APPROVED FOR PUBLICATION IN ACCORDANCE WITH THE ASSIGNED DISTRIBUTION STATEMENT.

*//Signature//

MARK GROFF
Program Manager
Business Operations Branch
Materials & Manufacturing Directorate

//Signature//

KENNETH A. FEESER
Branch Chief
Business Operations Branch
Materials & Manufacturing Directorate

This report is published in the interest of scientific and technical information exchange, and its publication does not constitute the Government's approval or disapproval of its ideas or findings.

^{*}Disseminated copies will show "//Signature//" stamped or typed above the signature blocks.

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

2. REPORT TYPE	3. DATES COVERED (From - To)		
Final	08 July 2005 – 01 February 2008		
4. TITLE AND SUBTITLE COLLABORATIVE RESEARCH AND DEVELOPMENT (CR&D)			
Delivery Order 0040: Bearing Health Monitoring Research and Development		5b. GRANT NUMBER	
		5c. PROGRAM ELEMENT NUMBER 62102F	
		5d. PROJECT NUMBER	
Sara Gudorf			
		5e. TASK NUMBER	
		L0	
		5f. WORK UNIT NUMBER	
		4349L0VT	
ND ADDRESS(ES)		8. PERFORMING ORGANIZATION REPORT NUMBER	
		S-531-040	
ME(S) AND ADDRESS(ES)		10. SPONSORING/MONITORING	
		AGENCY ACRONYM(S)	
torate	_	AFRL/RXOB	
OH 45433-7750		11. SPONSORING/MONITORING	
		AGENCY REPORT NUMBER(S) AFRL-RX-WP-TM-2010-4112	
		AI KL-KA- WF-1WI-2010-4112	
	Final AND DEVELOPMENT (CR&D) th Monitoring Research and Developmen ND ADDRESS(ES) ME(S) AND ADDRESS(ES)	Final 08 July 2 AND DEVELOPMENT (CR&D) th Monitoring Research and Development ND ADDRESS(ES) ME(S) AND ADDRESS(ES) torate	

12. DISTRIBUTION/AVAILABILITY STATEMENT

Approved for public release; distribution unlimited.

13. SUPPLEMENTARY NOTES

PAO Case Number: 88ABW 2010-1230; Clearance Date: 16 Mar 2010.

14. ABSTRACT

This research in support of the Air Force Research Laboratory Materials and Manufacturing Directorate was conducted at Wright-Patterson AFB, Ohio from 8 July 2005 through 1 February 2008. This task developed methodologies and performed health monitoring on advanced systems for aerospace applications to bearing materials. Coated bearings in high performance turbine engines can provide considerable advancements in engine reliability and service life extension. One coating performance indicator is the level of vibration generated by rolling elements and their cage separators at high speed bearing operation. Vibrations in engine bearings can be difficult to monitor because they are located in cramped spaces, and there is often system noise caused by other components located on the same shaft. A potential in-situ bearing health monitoring solution is a non-intrusive cage-mounted sensor that detects cage vibration and transmits wirelessly to a nearby receiver. This work describes the sensitivity of the cage-mounted sensor compared to a support-mounted accelerometer in the detection of seeded faults in coated and uncoated bearings.

15. SUBJECT TERMS

condition monitoring, Coated bearings, RF sensor

16. SECURITY CLASSIFICATION OF:		17. LIMITATION 18. NUMBER		19a. NAME OF RESPONSIBLE PERSON (Monitor)	
a. REPORT Unclassified	b. ABSTRACT Unclassified		OF ABSTRACT: SAR	OF PAGES 14	Mark Groff 19b. TELEPHONE NUMBER (Include Area Code) N/A

Standard Form 298 (Rev. 8-98) Prescribed by ANSI Std. Z39-18

Table of Contents

<u>Sec</u>	<u>tion</u>	<u>Page</u>
1.0	Introduction	1
2.0	Experimental Procedure	2
2.	1 Test Set-Up	2
2.	2 Uncoated Bearings	2
2.	3 Coated Bearings	2
3.0	Results and Discussion (also, 3.2 Sensitivity to Coating Failure)	3
3.	1 Sensitivity to Spalling	3
3.	2 Sensitivity to Coating Failure	3
3.	3 Signal Conditioning	4
3.	4 Future Work	4
4.0	Conclusion	5
5.0	References	6

Acknowledgement

The authors would like to thank Mr. Ryan Milligan with the Southwestern Ohio Council for Higher Education for running many of the bearing tests.

1.0 INTRODUCTION

Currently, aircraft engine bearings are replaced based on indirect inspection techniques such as chip detection and oil analysis. Each time an engine is torn down to replace a bearing, it grounds the aircraft and costs many thousands of dollars in materials and manpower. In the case of a bearing contamination failure characterized by a spalled bearing race, the effect is even more destructive and may result in engine shut-down and degradation of flight control. In extreme cases, the entire engine may be lost, resulting in millions of dollars in damage. A reliable and direct method is needed for bearing fault detection.

Many techniques have been used to diagnose bearing faults. High frequency methods include monitoring resonance, acoustic emissions [3] and shock pulse methods [4]. Low frequency detectors include accelerometers, fiber optic [5] and incremental motion encoders [6]. The problem with current fault diagnosis technologies is that they are bulky and not easily installed into the tight spaces of the jet engine. Many would also be susceptible to the high vibration environment and surrounding component noise level, and even fewer would be adaptable to the high temperatures required. Currently, many aircraft engines have chip detectors which are used to diagnose bearing failure [7,8]. But the chips have a convoluted path to get to the detectors, which are usually located far downstream from the bearing. Even when chips are detected, they may have come from another engine component and not necessarily from a failing bearing. Regardless, by the time large chips have spalled off and been caught in the detectors, the bearing is well on its way to failure. The benefit of the cage-mounted sensor is that it can more readily detect bearing motion because of its location on the cage (Figure 2). However, it does not detect vibration like an accelerometer. Instead, it measures cage motion relative to a nearby stationary receiver, and translates this motion into vibration. The cageembedded sensor transmits wirelessly to the receiver, and this direct method for detecting spalls has the potential to indicate a failing bearing at the first sign of trouble.

2.0 EXPERIMENTAL PROCEDURE

2.1 Test Set-Up

Trials were run on a specially-built high-speed bearing tester (Figure 3) at room temperature and pressure. The test bearing was a 25mm high speed angular contact bearing, chosen for its ease of assembly and disassembly. The phenolic cage was saturated with Pennzane® as the lubricant and all trials were run at the same temperature, load, pressure and duration. Vibration data was collected at shaft speeds of 0 to 10,000rpm every 500rpm. Sensor output was fed through a phase lock loop (PLL) demodulator to the oscilloscope. Accelerometer output was unfiltered and sent directly to the oscilloscope (Figure 4). Ten FFT averages helped to improve the signal-to-noise ratio, along with a 20MHz low-pass filter built into the oscilloscope. Finally, inner race fault frequencies were calculated using industry standard equations [9], and results from the sensor and housing-mounted accelerometer were compared to determine the minimum fault size detectable by each device.

2.2 Uncoated Bearings

An unflawed bearing was run to create a baseline vibration signals for the sensor and accelerometer. Then, flaws of 10µm, 28µm, 35µm, 50µm and 63µm were machined into the inner race of an uncoated bearing to simulate spalling (Figure 5), and vibration signatures were obtained using the sensor and accelerometer at each depth (Figure 6). Two sets of data were recorded for each spall depth to establish repeatability of the results. The spalls were machined using a precisely positioned drill bit to ensure perfect overlap, and a white light interferometer was used to measure depth in the wear track.

2.3 Coated Bearings

The inner and outer raceways of two unflawed test bearings were coated with TiCN to thicknesses of 0.4µm and 1.4µm, respectively, using a physical vapor deposition process. Each inner race was deposited with a 1/8" diameter mask to prevent coating in that area. After coating, the mask was removed during cleaning and the bearing re-assembled using the normal process. The flaw depth was the thickness of the coating; no additional spall was machined. A third coated bearing was unflawed with a thickness of ~1µm, and used for baseline testing. Two sets of vibration signatures were obtained using the sensor and accelerometer for each coating thickness. Coating thickness was measured using the white light interferometer at the site of the masked area (Figure 5).

3.0 RESULTS AND DISCUSSION (ALSO, 3.2 SENSITIVITY TO COATING FAILURE)

3.1 Sensitivity to Spalling

Both the sensor and the accelerometer detected the seeded faults in the uncoated bearing, but the accelerometer detected smaller flaws at a broader range of shaft speeds. The BPFI (inner race spall frequency) did not reliably appear in the sensor data until the spall was 28µm in depth (Figure 7). The sensor detected the 28µm flaw in just 38% of the tested motor speeds, and had a 60% detection rate for the 63µm spall. Therefore, although the amplitude of the BPFI did not increase with spall depth, it was detected at more shaft speeds, and was therefore more reliable as the spall size increased (Figure 8). However, the BPFI was often difficult to spot because its amplitude was often not much greater than the noise level.

The housing-mounted accelerometer exhibited a clear BPFI at most motor speeds, even for the smallest tested $10\mu m$ spall (Figure 9). Both the detection rate (Figure 8) and the BPFI amplitude remained nearly constant for each spall depth tested. The accelerometer was just as reliable in detecting the $10\mu m$ spall as the $63\mu m$ spall. The sensitivity limit of the accelerometer was not tested, but it detected the coated bearing flaw at $0.4\mu m$ and the average roughness of the coated bearing was $0.15\mu m$, so the lower detection limit of the accelerometer is assumed to be close to $0.4\mu m$. The detection rate of the accelerometer was not a perfect 100% because neither the sensor nor the accelerometer detected the flaws at the higher speeds near 10,000 rpm, and the accelerometer detected best at the lower speeds around 1000 rpm-4000 rpm.

3.2 Sensitivity to Coating Failure

The accelerometer successfully detected the missing coating on both the coated flawed bearings (Figure 10). It also was slightly more reliable in detecting the 1.4µm coating failure than the thinner coating (Figure 11). However, the cage sensor was unable to detect the coating flaw in either bearing and exhibited only healthy signatures (Figure 12). The large values in the 0.4µm and 1.4µm flawed bearings are probably a harmonic of the cage rotation rate and not detection of the spall.

Increasing the coating thickness beyond 1.4µm was not considered due to space and durability restraints. Previous studies report that bearing coatings thicker than 2µm tend to delaminate and flake off during operation [10]. In addition, too thick a coating will increase stiffness and wear rates and decrease the life of the bearing. Therefore, the sensor was judged

ineffective in detecting coating failure, not surprising since the sensor did not identify a spall in the uncoated bearing until it was 28µm deep.

3.3 Signal Conditioning

In an attempt to optimize the sensor output, first and fifth-order Butterworth low-pass filters were built to amplify the small sensor signal and minimize high-frequency noise. Both successfully boosted the signal to the oscilloscope. However, they also increased the noise level by acting as a magnifier of electricity and room noise. The sensor signal was amplified, but consequently drowned out by the similarly amplified noise. This was determined not to improve the effectiveness of the cage sensor and the filters were removed.

Separately, a low noise amplifier was installed on the sensor output to boost the small signal from the sensor before it is demodulated. In theory, this would increase the output from the demodulator while keeping the noise level the same. The result was a complete loss of output from the demodulator. The low noise amplifier (LNA) was unable to transmit the 30MHz output from the sensor to the demodulator. Even though the signal of interest, the BPFI, is on the order of 1kHz, the output from the sensor is in the MHz. Without the full input from the sensor, the demodulator was unable to output the BPFI, so the LNA was removed.

3.4 Future Work

Future work will include installing a high-frequency low-noise amplifier which will boost sensor power after telemetry but before demodulation to increase the sensor signal-to-noise ratio. Also, additional trials are needed to establish repeatability, including changing the diameter of the spall. Additional sensors are being fabricated and it will be important to determine repeatability between sensors. The circuitry on the receiver is very susceptible to input power and has been overloaded several times. Comparing the results from a new circuit board with the one used in these trials will be very helpful in determining robustness and whether this sensor used in these trials was fully functional.

4.0 CONCLUSION

The smallest spall on an uncoated bearing that the sensor detected was 28µm with a reliability of 38%. The sensor was unable to detect the coating failure at all. In contrast, the accelerometer reliably detected all levels of flaws, the smallest being 10µm on the uncoated bearing and 0.4µm on the coated bearing, with a minimum reliability of 78% for the uncoated bearing and 53% for the coated bearing. This research successfully demonstrated that the sensor could detect bearing spalls and established its sensitivity level. In the next generation of sensor, the receiver temperature capability will be increased. With further advances in miniaturization, sensitivity, temperature and transmission ranges, the cage-mounted sensor may become a reliable and direct approach for engine bearing health monitoring.

5.0 REFERENCES

- [1] A. Rodwell, Engine Bearing Failure Detection Improved with New Technology, *Flying Safety* 7 (2002) 24-25.
- [2] S. Marble, D. Tow, Bearing Health Monitoring and Life Extension in Satellite Momentum/Reaction Wheels, *IEEEAC*, Paper #1352 (2006).
- [3] C. James Li, S.Y. Li, Acoustic emission analysis for bearing health monitoring, *Journal of Wear* 185 (1995) 67-74.
- [4] N. Tandon, A. Choudhury, A review of vibration and acoustic measurement methods for the detection of defects in rolling element bearings, *Tribology International* 32 (1999) 469-480.
- [5] R.W. Gamache, A prototype fiberoptic deflectometer for SSME turbopump bearing health monitoring, *NASA STI/Recon Technical Report A* 95 (1993).
- [6] K. Ayandokun, P.A Orton, N.Sherkat, P.D. Thomas, Detecting rolling element bearing defects with the optical incremental motion encoder, *SPIE Proceedings* 2349 (1995) 53-64.
- [7] J.L. Miller, D. Kitaljevich, In-Line Oil Debris Monitor for Aircraft Engine Condition Assessment, *IEEE 0-7803-5846-5* (2000).
- [8] B.T. Holm-Hanson, R.X. Gao, Integrated Microsensor Module for a Smart Bearing with On-Line Fault Detection Capabilities, *IEEE 0-7803-3312-8* (1997).
- [9] H. Ocak, K.A. Loparo, Estimation of the running speed and bearing defect frequencies of an induction motor from vibration data, *Mechanical Systems and Signal Processing* 18 (2004) 515-533.
- [10] A. Erdemir, Rolling-contact fatigue and wear resistance of hard coatings on bearing-steel substrates, *Surface and Coatings Technology* 54/55 (1992) 482-489.